

SURFACE INSPECTION REPORT

DEP USE ONLY Inspection Record No. 3762896

Complaint Record No. Enforcement Record No.

DEP Office	California Oil & Gas Office	Inspection Type	Site
Address	25 Technology Drive, California Technology Park	Permit or Reg. #	
Addr Cont	Coal Center, PA 15423	ESCGP#	ESG076322002-00
Oper. Name	EQT PROD CO	Site #	813604
Oper. Address	400 WOODCLIFF DR CANONSBURG, PA 15317-5851	Project#	
Resp. Official Name		Farm Name & Well #	MINGO WELL SITE ESCGP-2 EXPEDITED
Resp. Official Phone		Other Info	
Latitude		Longitude	
County	Washington	Municipality	Union Township
Inspection Code	RTPT - Routine/Partial Inspection	Facility	
Permits/Auths	ESCGP	Site Phase	Restored/Prod
Well Info		Well Kind & Description	



5500-FM-OG0114(M) 06/2021

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL **PROTECTION**

SURFACE INSPECTION REPORT

DEP USE ONLY

No.

Inspection Record No. 3762896

Complaint Record | Enforcement Record No.

GENERAL COMMENTS

On 05/15/2024, a routine partial inspection was conducted at the Mingo Well Site. NWE crew onsite.

Permit ESG076322002-00 expires on 02/22/2028.

The following was observed:

Sediment Control

Act 9 sign at site entrance. PPC plan and ERP in mailbox (Photo 1). The site has been constructed, however no wells have been drilled.

A slope failure, discovered by the Department, had occured on the northern fill slope of the pad. The slope failure looked to have had surface sloughing. The failure was approximately 50 feet in length, approximately 15-20 feet in width, and with an escarpment of approximately one foot (Photos 2-5).

The toe of the failure was displaying an escarpment of approximately 1 foot (Photos 6, 7).

There was additional surface sloughing below the failure area which appeared to be approximately 25 feet in length and approximately 10-15 feet in width (Photos 8, 9).

The filter sock at the base of the slope appeared to require maintenance as sediment has accumulated (Photo 10).

WOC do not appear to be impacted by this failure and the well pad does not appear to be affected.

Due to the discovery of a slope failure, violations of 102.5(m)4, 102.22(a), 78a53, 102.11(a), and 102.4(b)1 are being issued.

REMARKS / VIOLATIONS					
Category	Sub-Category	Inspection Remarks / Violations / Violation Remarks	ı	R	٧
Erosion &					



SURFACE INSPECTION REPORT

DEP USE ONLY

Inspection Record No. 3762896

Complaint Record No. Enforcement Record No.

1: E & S Control Requirements: E	Inspection Remark:	✓	✓
& S Control			
Requirements			
NEW	Violation:78a53 - EROSION AND SEDIMENT CONTROL AND		
	STORMWATER MANAGEMENT - Person proposing or conducting		
	earth disturbance activities associated with oil and gas operations		
	failed to comply with 25 Pa. Code § 102.		
	Violation Date: 2024-05-15		
	Violation Remarks: See narrative		
NEW	Violation:102.11(a)1 - GENERAL REQUIREMENTS – BMP AND		
	DESIGN STANDARDS - Person failed to design, implement and		
	maintain E & S BMPs to minimize the potential for accelerated		
	erosion and sedimentation to protect, maintain, reclaim and restore		
	water quality and existing and designated uses.		
	Violation Date: 2024-05-15		
	Violation Remarks: See narrative		
NEW	Violation:102.4(b)1 - EROSION AND SEDIMENT CONTROL		
	REQUIREMENTS - Person conducting earth disturbance activity		
	failed to implement and maintain E & S BMPs to minimize the		
	potential for accelerated erosion and sedimentation.		
	Violation Date: 2024-05-15		
	Violation Remarks: See narrative		
1: E & S Permit	Inspection Remark:	✓	✓
Requirements: E			
& S Permit			
Requirements			
NEW	Violation:102.5(m)4 - PERMIT REQUIREMENTS – GENERAL		
	PERMITS – Person failed to comply with the terms and conditions of		
	the E & S Control General Permit.		
	Violation Date: 2024-05-15		
	Violation Remarks: See narrative		



SURFACE INSPECTION REPORT

DEP USE ONLY

No.

Inspection Record No. 3762896

Complaint Record **Enforcement Record** No.

1: Site	Inspection Remark:		/
Stabilization: Site			
Stabilization			
NEW	Violation:102.22(a) - SITE STABILIZATION – PERMANENT		
	STABILIZATION – Permitee failed to have site permanently stabilized		
	and protected from accelerated erosion and sedimentation upon final		
	completion of earth disturbance activity.		
	Violation Date: 2024-05-15		
	Violation Remarks: See narrative		

Inspection Results	Files Attached	Photos Attached	Date Inspected
VIOLS - Violation(s) Noted		\checkmark	05/15/2024



SARA TRIO, Water Quality Specialist

Arrival: 05/15/2024 08:39:00 AM, Departure: 05/15/2024 09:30:00 AM



5500-FM-OG0114(M) 06/2021

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL **PROTECTION**

SURFACE INSPECTION REPORT

DEP USE ONLY

No.

Complaint Record

Enforcement Record No.

Inspection Record

No.

3762896

NOTICE OF VIOLATION(S)			
Citation	Description of Violation		
25 Pa. Code § 78a.53	78a53 - EROSION AND SEDIMENT CONTROL AND STORMWATER MANAGEMENT - Person proposing or conducting earth disturbance activities associated with oil and gas operations failed to comply with 25 Pa. Code § 102.		
25 Pa. Code § 102.11(a)1	102.11(a)1 - GENERAL REQUIREMENTS – BMP AND DESIGN STANDARDS - Person failed to design, implement and maintain E & S BMPs to minimize the potential for accelerated erosion and sedimentation to protect, maintain, reclaim and restore water quality and existing and designated uses.		
25 Pa. Code § 102.4(b)1	102.4(b)1 - EROSION AND SEDIMENT CONTROL REQUIREMENTS - Person conducting earth disturbance activity failed to implement and maintain E & S BMPs to minimize the potential for accelerated erosion and sedimentation.		
25 Pa. Code § 102.5(m)4	102.5(m)4 - PERMIT REQUIREMENTS – GENERAL PERMITS – Person failed to comply with the terms and conditions of the E & S Control General Permit.		
	102.22(a) - SITE STABILIZATION – PERMANENT STABILIZATION – Permitee failed to		

Note: This Notice of Violation is neither an order nor any other final action of the Department of Environmental Protection. It neither imposes nor waives any enforcement action available to the Department under any of its statutes. If the Department determines that an enforcement action is appropriate, you will be notified of the action.

have site permanently stabilized and protected from accelerated erosion and

sedimentation upon final completion of earth disturbance activity.

58 Pa.C.S. § = Act 13(OGA) • 25 Pa.Code § • 35 P.S. § 6018. = Solid Waste Management Act • 35 P.S. § 691. = Clean Streams Law

MAILED BY	CERT MAIL#	MAIL DATE

INSTRUCTIONS RESPONSE

25 Pa. Code § 102.22(a)

- You are requested to respond as indicated below by 05/31/2024. If applicable, please include the description of activities you will pursue to achieve compliance with the statutes or regulations cited above. Address your reply to the DEP representative named below.
 - No further response required at this time.
- Written response requested
- Has to be done (Specify in the comment section below)
- Add what you will do to correct the situation and achieve compliance?
- Include explanation of cause of violations
- Include the schedule or anticipated time frame for compliance activities you intend to carry out



SURFACE INSPECTION REPORT

DEP USE ONLY Inspection Record No. 3762896

Complaint Record No. Enforcement Record No.

v1.2.18

RESPONSE COMMENTS

What is being done in the interim (temporary stabilization)

What is being done in the future (permanent stabilization)

The Department requests that a Geotechnical Report be submitted to Technical Services

The Department recommends that the Operator works with Technical Services for any Potential Modification of Permit to address Slope Failure(s)

Please provide an electronic copy of the NOV response to WQS Sara Trio (strio@pa.gov), WQSS Sam Steingrabe (ssteingrab@pa.gov), and EGM Alex Barravecchio (abarravecc@pa.gov).



SURFACE INSPECTION REPORT

DEP USE ONLY

No.

No. 3762896

Complaint Record Enforcement Record No.

Inspection Record

INSPECTION IMAGES





#: 1

Act 9 sign

#: 2

Approximately 50 feet in length



SURFACE INSPECTION REPORT

DEP USE ONLY

No.

Inspection Record No. 3762896

Complaint Record Enforcement Record No.





Approximately 15-20 feet in width

#: 3

#: 4

Scarp approximately 1 foot



SURFACE INSPECTION REPORT

DEP USE ONLY

3762896

Inspection Record

No.

Complaint Record Enforcement Record No. No.





#: 5 #: 6

Failure area Toe of failure



5500-FM-OG0114(M) 06/2021

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL **PROTECTION**

SURFACE INSPECTION REPORT

DEP USE ONLY

No.

Inspection Record No. 3762896

Complaint Record Enforcement Record No.

v1.2.18





#: 7 #: 8

Toe of failure

Lower sloughing



SURFACE INSPECTION REPORT

DEP USE ONLY

3762896 rd Enforcement Record

Inspection Record

No.

Complaint Record No. Enforcement Record No.

ANT.		
	Cart	
	The state of	Action Alexander
	Fall Control	
× +1.) 4.7	Lat: 40.23195, Long: -7	9.98694 05/15/2024 08:48:44 AM



#: 9 #: 10

Lower sloughing Sock at base of slope