

**INSPECTION REPORT ROUTINE
 INSPECTION**
**DEP USE
 ONLY**

 Inspection Record
 No.
 3600679

 Complaint Record
 No.

 Enforcement Record
 No.

DEP Office	Southwest Oil & Gas District Office		Telephone No.: (412) 442-4024	Permit or Reg. No.:	003-00963		
Address	400 Waterfront Drive		Fax No.: ----	Project No.: ----	WellPad: ----		
	Pittsburgh, PA 15222-4745			Farm Name and Well No.:	NIXON 501-4		
Operator Name	MICHAEL HARJU			County	Allegheny		
Address	PO BOX 23 SPRING CHURCH, PA 15686-0023			Municipality	Scott Township		
	----			Latitude (DD)	40.382806		
OGO No.	OGO-36206	Client ID No.	93301	Longitude (DD)	-80.074806		
Drilling Rig / Type	----						
Facility Type	----		Producing Formation	----			
Other	<input type="checkbox"/> Permit Expired	<input type="checkbox"/> Alt / Meth	<input type="checkbox"/> Annulus Open	<input type="checkbox"/> Conductor Only	Spud Date: 1800-01-01	<input type="checkbox"/> Coal	<input checked="" type="checkbox"/> Non-Coal

Remarks / Violations					
Category	Sub-Category	Inspection Remarks / Violations / Violation Remarks	I	R	V
Location					
Well					
Waste Management					
Other					

WELL INFORMATION					
Well Status:		Well Production Status:		Well Type:	Depth: ft.
Flowback: <input type="checkbox"/> Yes <input type="checkbox"/> No		Stressed Vegetation: <input type="checkbox"/> Yes <input type="checkbox"/> No		Wells on Location:	
Separators: <input type="checkbox"/> Yes <input type="checkbox"/> No		Oil Staining: <input type="checkbox"/> Yes <input type="checkbox"/> No			

Casing	Size			Press (psi)	Volumn (cu ft/d)	Length (ft)	SIPT
1	--- X ---			---	---	---	<input type="checkbox"/>
	0 Hrs: ---	12 Hrs: ---	24 Hrs: ---	48 Hrs: --- -	72 Hrs: ---	Days: ---, ---	
	Casing: ---			Volumn: ---			
	Gas Detected: --- -	Gas Concentation: ---% LEL, ---% GAS		Method Used: ---		Date Calibrated: --- -	
	Additional Comments: ---						

Cellar Observation			
Water	<input type="checkbox"/> Yes <input type="checkbox"/> No	Below Grade:	Combustible Gas Detected <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unable to check for gas
Gravel	<input type="checkbox"/> Yes <input type="checkbox"/> No	Below Grade:	
Bubbling	<input type="checkbox"/> Yes <input type="checkbox"/> No	Rate:	Gas Concentration: % LEL, % GAS
			Method Used:
			Date Calibrated:

EQUIPMENT ON LOCATION			
Equipment on Location		Tanks: []	
Dryers:	Drips:	Brine/Oil:	Fresh Water:
Pumpjacks:	Meters:	Flowback:	Consolidation:
Separators:	Containment:	Propane:	Poly Vent:
Compressors:		Production:	

RTN Other Data			
H2S Detected	<input type="checkbox"/> Yes <input type="checkbox"/> No	ppm	Corrosion: Leaking:

Photos Attached	Additional Documents	WQS follow up	Inspection Results
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No	ICS - In Compliance with Schedule



v1.2.13

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION OFFICE OF OIL AND GAS

**INSPECTION REPORT ROUTINE
INSPECTION**

**DEP USE
ONLY**

Complaint Record
No.

Inspection Record
No.
3600679

Enforcement Record
No.

Remarks:

Met with representatives of Yost and Stahl Sheaffer Engineering to evaluate what will be needed to plug the well. Well is unchanged from prior visits.

On Site Representative



(signature)

(print name)

DEP Representative

(signature)

MARK E BARNES, OIL GAS INSP

(print name)

Date: 08/15/2023

Time Arrived: 11:05 AM

Time Departed: 11:40 AM

INSPECTION IMAGES



Lat: 40.38277, Long: -80.07481 08/15/2023 11:08:57 AM

#: 1

Well and vent.



Lat: 40.38282, Long: -80.07479 08/15/2023 11:09:48 AM

#: 2

Well, vent and Scrubgrass Road.