

DEP Office	New Stanton Oil & Gas Office	Inspection Type	Site
Address	131 Broadview Road	Permit or Reg. #	----
Addr Cont	New Stanton, PA 15672	ESCGP #	ESG070419010-01
Oper. Name	ETC NORTHEAST PIPELINE LLC	Site #	817832
Oper. Address	6051 WALLACE RD EXT SUITE 300 WEXFORD, PA 15090-7376	Project #	----
Resp. Official Name		Farm Name & Well #	REVOLUTION PIPELINE
Resp. Official Phone		Other Info	----
Latitude	----	Longitude	----
County	Beaver	Municipality	Independence Township
Inspection Code	FUI - Follow-up Inspection	Facility	Pipeline
Permits/Auths	ESCGP	Site Phase	Restored/Prod
Well Info	----	Well Kind & Description	----

GENERAL COMMENTS

On May 15, 2024, the Department conducted a follow up inspection at STA 1777+25 in response to IR 3760872 and the following email from ETC received by the Department on 5/10/2024:

"ETC is providing an update to all the recent features that were observed on the Revolution Pipeline. Please see below: It is important to note that there are currently no pipeline integrity concerns.

...1777+25:

Monitoring stakes installed.

4.0" movement measured total.

Access route survey, wetland survey, wildcat probes completed.

Next Steps:

Continue monitoring 5-days per week (Monday – Friday).

Obtain access agreement with landowner.

Landowner contact continues for alternative access.

Develop a repair plan."

Accompanying me today is Tyler Metzger (DEP).

No new cracking was observed from the Department's previous inspection on 5/9/2024.

Five stakes with white flagging have been installed marked as DCP-1, DCP-2, DCP-3, DCP-4, and DCP-5. The stakes are dated 5/3/2024 and are presumably marking wildcat probe locations.

Violations remain outstanding.

REMARKS / VIOLATIONS

Category	Sub-Category	Inspection Remarks / Violations / Violation Remarks	I	R	V
----------	--------------	---	---	---	---

Pipelines	1: Gathering Pipelines: Gathering Pipelines	Inspection Remark: <hr/> CONTINUE Violation: 8183046, eFACTS Date Of: 04/08/2024 78a68(a) - OIL AND GAS GATHERING PIPELINES - Construction, installation, use, maintenance, repair and removal of oil and gas gathering pipelines failed to be conducted in accordance with the requirements of 25 Pa. Code Chapters 102 and 105. Violation Date: 2024-05-15 Violation Remarks: Tension cracks at STA 1777+25	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>
Spills & Releases	1: Clean Streams Law: Clean Streams Law	Inspection Remark: <hr/> CONTINUE Violation: 8183047, eFACTS Date Of: 04/08/2024 CSL 402(b) - POTENTIAL POLLUTION - Conducting an activity regulated by a permit issued pursuant to Section 402 of The Clean Streams Law to prevent the potential of pollution to waters of the Commonwealth without a permit or contrary to a permit issued under that authority by the Department. Violation Date: 2024-05-15 Violation Remarks: Slope failure at STA 1777+25 above INT Stream 9-133 (UNT to Potato Garden Run)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>
Erosion & Sediment Control	1: E & S Control Requirements: E & S Control Requirements	Inspection Remark: <hr/> CONTINUE Violation: 8183042, eFACTS Date Of: 04/08/2024 78a53 - EROSION AND SEDIMENT CONTROL AND STORMWATER MANAGEMENT - Person proposing or conducting earth disturbance activities associated with oil and gas operations failed to comply with 25 Pa. Code ? 102. Violation Date: 2024-05-15 Violation Remarks: Tension cracks at STA 1777+25	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>

1: E & S Permit Requirements: E & S Permit Requirements		Inspection Remark:	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>
CONTINUE	Violation: 8183043, eFACTS Date Of: 04/08/2024 102.5(m)4 - PERMIT REQUIREMENTS ? GENERAL PERMITS ? Person failed to comply with the terms and conditions of the E & S Control General Permit. Violation Date: 2024-05-15 Violation Remarks: Tension cracks at STA 1777+25		
1: Site Stabilization: Site Stabilization		Inspection Remark:	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>
CONTINUE	Violation: 8183044, eFACTS Date Of: 04/08/2024 102.22(a) - SITE STABILIZATION ? PERMANENT STABILIZATION ? Permittee failed to have site permanently stabilized and protected from accelerated erosion and sedimentation upon final completion of earth disturbance activity. Violation Date: 2024-05-15 Violation Remarks: Tension cracks at STA 1777+25		
CONTINUE	Violation: 8183045, eFACTS Date Of: 04/08/2024 102.22(b)1 - SITE STABILIZATION ? TEMPORARY STABILIZATION ? Permittee failed to temporarily stabilize the site to protect it from accelerated erosion and sedimentation where cessation of earth disturbance activities exceeded 4 days. Violation Date: 2024-05-15 Violation Remarks: Tension cracks at STA 1777+25		

Inspection Results	Files Attached	Photos Attached	Date Inspected
OUTST - Outstanding Violations - Viols Req'd	<input type="checkbox"/>	<input checked="" type="checkbox"/>	05/15/2024



v2024.2.1

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL
PROTECTION

SURFACE INSPECTION REPORT

**DEP USE
ONLY**

Inspection Record
No.
3763550

Complaint Record
No.

Enforcement Record
No.

SIGNATURE

NICHOLAS DEEMER, Water Quality Specialist

Arrival: 05/15/2024 12:40:00 PM, Departure: 05/15/2024 12:55:00 PM

ADDITIONAL INSPECTORS

TYLER METZGER

NOTICE OF VIOLATION(S)

Citation	Description of Violation
25 Pa. Code § 78a.68(a)	OIL AND GAS GATHERING PIPELINES - Construction, installation, use, maintenance, repair and removal of oil and gas gathering pipelines failed to be conducted in accordance with the requirements of 25 Pa. Code Chapters 102 and 105.
35 P.S. § 691.402(b)	POTENTIAL POLLUTION - Conducting an activity regulated by a permit issued pursuant to Section 402 of The Clean Streams Law to prevent the potential of pollution to waters of the Commonwealth without a permit or contrary to a permit issued under that authority by the Department.
25 Pa. Code § 78a.53	EROSION AND SEDIMENT CONTROL AND STORMWATER MANAGEMENT - Person proposing or conducting earth disturbance activities associated with oil and gas operations failed to comply with 25 Pa. Code ? 102.
25 Pa. Code § 102.5(m)4	PERMIT REQUIREMENTS ? GENERAL PERMITS ? Person failed to comply with the terms and conditions of the E & S Control General Permit.
25 Pa. Code § 102.22(a)	SITE STABILIZATION ? PERMANENT STABILIZATION ? Permittee failed to have site permanently stabilized and protected from accelerated erosion and sedimentation upon final completion of earth disturbance activity.
25 Pa. Code § 102.22(b)1	SITE STABILIZATION ? TEMPORARY STABILIZATION ? Permittee failed to temporarily stabilize the site to protect it from accelerated erosion and sedimentation where cessation of earth disturbance activities exceeded 4 days.

Note: This Notice of Violation is neither an order nor any other final action of the Department of Environmental Protection. It neither imposes nor waives any enforcement action available to the Department under any of its statutes. If the Department determines that an enforcement action is appropriate, you will be notified of the action.

58 Pa.C.S. § = Act 13(OGA) • 25 Pa.Code § • 35 P.S. § 6018. = Solid Waste Management Act • 35 P.S. § 691. = Clean Streams Law

MAILED BY	CERT MAIL#	MAIL DATE

INSTRUCTIONS RESPONSE

- You are requested to respond as indicated below by . If applicable, please include the description of activities you will pursue to achieve compliance with the statutes or regulations cited above. Address your reply to the DEP representative named below.
- No further response required at this time.
- Not Applicable

INSPECTION IMAGES



#: 1

Head scarp



#: 2

Set 1 monitoring stakes at head scarp



#: 3

Head scarp and set 1 monitoring stakes



#: 4

Set 1 monitoring stakes at head scarp with bore DCP-1 stake



#: 5

Head scarp in center of photo with Set 1 upslope



#: 6

DGP-2 near downslope cracking, Set 2 monitoring stakes



#: 7

Set 2 monitoring stakes



#: 8

Set 2 monitoring stakes



#: 9

DCP-5 near downslope cracking. Set 2 monitoring stake on right for reference



#: 10

DCP-4 in foreground, DCP-3 further away

DEP USE ONLY
Complaint Record No.

Inspection Record No. 3763550
Enforcement Record No.



#: 11

Overview